

CHAPTER 32: REPAIR WORKS						
Item No.	Description of Item	Unit	Unit Rate (Dhaka, Mymensingh)	Unit Rate (Chattogram, Sylhet)	Unit Rate (Khulna, Barisal, Gopalganj)	Unit Rate (Rajshahi, Rangpur)
32.1	Stripping of unserviceable plaster including racking out joints, cleaning etc.	sqm	Tk. 31.00	Tk. 30.00	Tk. 28.00	Tk. 28.00
32.2.1	Picking-up of unserviceable patent stone from floor and dado etc. and removal of debris to a safe distance.	sqm	Tk. 47.00	Tk. 45.00	Tk. 43.00	Tk. 43.00
32.2.2	Picking-up of unserviceable tiles including bonding mortar from floor, walls and dado etc. and removal of debris to a safe distance.	sqm	Tk. 61.00	Tk. 60.00	Tk. 56.00	Tk. 56.00
32.3	Picking up of damaged/unserviceable terraced (lime concrete) floor or roof etc. and removal of debris to a safe distance.	sqm	Tk. 65.00	Tk. 63.00	Tk. 59.00	Tk. 59.00
32.4	Dismantling of unserviceable/damaged terraced roof including beam, column, barga & tiles etc. and removal of debris to a safe distance.	sqm	Tk. 164.00	Tk. 161.00	Tk. 153.00	Tk. 153.00
32.5.1.1	Dismantling of unserviceable/damaged brick works (with cement or lime mortar) of thickness 250 mm in foundation and superstructure and removal of debris to a safe distance.	cum	Tk. 538.00	Tk. 524.00	Tk. 491.00	Tk. 491.00
32.5.1.2	Dismantling of unserviceable/damaged brick works (with cement or lime mortar) of thickness 75/125 mm in foundation and superstructure and removal of debris to a safe distance.	sqm	Tk. 62.00	Tk. 61.00	Tk. 57.00	Tk. 57.00
32.5.2	Dismantling of plain concrete made of lime or cement and removal of debris to a safe distance.	cum	Tk. 1,647.00	Tk. 1,606.00	Tk. 1,503.00	Tk. 1,503.00
32.5.3	Dismantling of brick flat soling and removal of debris to a safe distance and removal of debris to a safe distance.	sqm	Tk. 18.00	Tk. 17.00	Tk. 16.00	Tk. 16.00
32.5.4	Dismantling of H.B.B. Brick soling and removal of debris to a safe distance and removal of debris to a safe distance.	sqm	Tk. 24.00	Tk. 23.00	Tk. 21.00	Tk. 21.00
32.6.1.1	Dismantling of R.C.C. beam, lintel, column, drop wall, sun shade from any height and removal of debris to a safe distance.	cum	Tk. 3,928.00	Tk. 3,841.00	Tk. 3,612.00	Tk. 3,612.00
32.6.1.2	Dismantling of R.C.C. Railing of any kind, jally brickwork, and hollow block wall from any height and removal of debris to a safe distance.	sqm	Tk. 218.00	Tk. 214.00	Tk. 202.00	Tk. 202.00
32.6.2	Dismantling of R.C.C. in roof slab and removal of debris to a safe distance.	cum	Tk. 3,319.00	Tk. 3,244.00	Tk. 3,065.00	Tk. 3,065.00
32.6.3	Recovery of reinforcing bars and metals during dismantling of RCC including cleaning, making bundle, stacking or storing as per direction of engineer in charge and removal of debris to a safe distance.	quintal	Tk. 552.00	Tk. 540.00	Tk. 503.00	Tk. 503.00
32.6.4	Recovery of bricks during dismantling of brick works including cleaning, stacking or storing etc. all complete as per direction of engineer in charge and removal of debris to a safe distance.	% 0 nos	Tk. 1,485.00	Tk. 1,458.00	Tk. 1,350.00	Tk. 1,350.00
32.6.5	Recovery of bricks during dismantling of soling including cleaning, stacking or storing all complete as per direction of engineer in charge and removal of debris to a safe distance.	% 0 nos	Tk. 999.00	Tk. 981.00	Tk. 908.00	Tk. 908.00
32.6.6	Recovery of brick bats during dismantling of soling, brick works, HBB etc. including cleaning, stacking or storing as per direction of engineer in charge and removal of debris to a safe distance.	cum	Tk. 250.00	Tk. 245.00	Tk. 227.00	Tk. 227.00
32.7	Repairs to minor/fine (non-structural affecting aesthetic) cracks in brick walls, floor and roof etc.	meter	Tk. 42.00	Tk. 41.00	Tk. 38.00	Tk. 38.00
32.8.1	Cutting and polishing of old mosaic on wall with pumice stone etc.	sqm	Tk. 100.00	Tk. 98.00	Tk. 92.00	Tk. 92.00

Handwritten signatures and initials in blue ink are present at the bottom of the page, including names like 'Anwar' and various initials.

Item No.	Description of Item	Unit	Unit Rate (Dhaka, Mymensingh)	Unit Rate (Chattogram, Sylhet)	Unit Rate (Khulna, Barisal, Gopalganj)	Unit Rate (Rajshahi, Rangpur)
32.8.2	Cutting and polishing of old mosaic on floor with pumice stone and mosaic cutting machine etc.	sqm	Tk. 112.00	Tk. 110.00	Tk. 106.00	Tk. 106.00
32.8.3	Cleaning and washing the mosaic floor etc.	sqm	Tk. 20.00	Tk. 19.00	Tk. 18.00	Tk. 18.00
32.8.4	Cleaning and refilling of wornout joints between glazed tiles, marble etc. in floor or walls.	sqm	Tk. 71.00	Tk. 69.00	Tk. 65.00	Tk. 65.00
32.9	Repairing of terraced roof cracks by cutting in 'trapezoidal' shape	meter	Tk. 539.00	Tk. 531.00	Tk. 501.00	Tk. 500.00
32.10	Taking out and relaying of old brick soling including replacement of 10% brick	sqm	Tk. 128.00	Tk. 127.00	Tk. 120.00	Tk. 119.00
32.11	Taking out and relaying of brick soling after redressing the surfaces	sqm	Tk. 85.00	Tk. 84.00	Tk. 78.00	Tk. 78.00
32.12.1	Taking out of old brick on edge pavement and resetting (Herring bone bond) including replacement of 10% brick	sqm	Tk. 210.00	Tk. 208.00	Tk. 197.00	Tk. 196.00
31.12.2	Taking out of old brick on edge pavement and resting Herring bone bond and redressing the surface	sqm	Tk. 117.00	Tk. 116.00	Tk. 107.00	Tk. 107.00
32.13	Taking out of old roof tiles and ridges	sqm	Tk. 67.00	Tk. 65.00	Tk. 61.00	Tk. 61.00
32.14	Supplying and fitting-fixing of wind tie with M.S. Flat bar clamp	meter	Tk. 565.00	Tk. 562.00	Tk. 550.00	Tk. 550.00
32.15	Supplying and fitting-fixing of J-hook including nuts, washers	each	Tk. 49.00	Tk. 49.00	Tk. 48.00	Tk. 48.00
32.16	Supplying and fitting-fixing of M.S. U-hook including nuts, washers	each	Tk. 64.00	Tk. 64.00	Tk. 63.00	Tk. 63.00
32.17	Taking out of old & unserviceable wooden chowkat /door or window frame	each	Tk. 328.00	Tk. 318.00	Tk. 301.00	Tk. 301.00
32.18	Taking out of old wooden chowkat/door or window frame and refitting and refixing after minor repair (excluding the cost of wood and M.S. clamp)	each	Tk. 1,058.00	Tk. 1,042.00	Tk. 972.00	Tk. 972.00
32.19	Taking out and refitting of wooden shutter after easing excluding the cost of wood	sqm	Tk. 450.00	Tk. 445.00	Tk. 413.00	Tk. 413.00
32.20.1	Thorough repairs to wooden door and window Pannel shutter excluding the cost of wood	sqm	Tk. 730.00	Tk. 723.00	Tk. 672.00	Tk. 672.00
32.20.2	Thorough repairs to wooden door and window Batten shutter excluding the cost of wood	sqm	Tk. 677.00	Tk. 671.00	Tk. 626.00	Tk. 626.00
32.20.3	Thorough repairs to wooden door and window Venetian shutter excluding the cost of wood	sqm	Tk. 657.00	Tk. 651.00	Tk. 605.00	Tk. 605.00
32.20.4	Thorough repairs to wooden door and window Glazed shutter excluding the cost of glass & wood	sqm	Tk. 627.00	Tk. 622.00	Tk. 578.00	Tk. 578.00
32.21.1	Renewing of 3 mm glass panes in wooden frame including supply of glass	sqm	Tk. 1,024.00	Tk. 1,020.00	Tk. 1,000.00	Tk. 1,000.00
32.21.2	Renewing of 3 mm glass panes in steel frame including supply of glass	sqm	Tk. 1,130.00	Tk. 1,125.00	Tk. 1,103.00	Tk. 1,103.00
32.22	Renewing of 5 mm glass panes including supply of glass	sqm	Tk. 1,348.00	Tk. 1,344.00	Tk. 1,329.00	Tk. 1,329.00
32.23	Cleaning and washing of glass panes including supply of necessary fresh putty, pins etc.	per pane	Tk. 4.00	Tk. 3.00	Tk. 3.00	Tk. 3.00
32.24.1	Replacing / renewing of fly proof wire net (with all new materials) the excluding cost of wood	sqm	Tk. 768.00	Tk. 767.00	Tk. 726.00	Tk. 726.00
32.24.2	Replacing / renewing of synthetic fly proof net (with all new materials) the excluding cost of wood	sqm	Tk. 795.00	Tk. 795.00	Tk. 753.00	Tk. 753.00
32.25	Renewing of fly proof wire netting (with old and new materials) the excluding cost of wood	sqm	Tk. 737.00	Tk. 736.00	Tk. 695.00	Tk. 695.00
32.26	Renewing of 12 x 12 mm mesh wire netting the excluding cost of wood	sqm	Tk. 630.00	Tk. 629.00	Tk. 595.00	Tk. 595.00
32.27	Taking out of hard board ceiling, walling	sqm	Tk. 22.00	Tk. 21.00	Tk. 20.00	Tk. 20.00
32.28	Renewing of hard board ceiling or walling excluding cost of wood	sqm	Tk. 657.00	Tk. 656.00	Tk. 628.00	Tk. 628.00
32.29	Replacing of wooden cleat, making, finishing and fixing with chowkat by means of 40 mm hinge	each	Tk. 80.00	Tk. 79.00	Tk. 79.00	Tk. 79.00
32.30	Replacing of cleat with brass hinge	each	Tk. 89.00	Tk. 88.00	Tk. 87.00	Tk. 87.00
32.31	Replacing of wooden buffer block	each	Tk. 60.00	Tk. 59.00	Tk. 59.00	Tk. 59.00
32.32	Replacig of wooden catcher block	each	Tk. 88.00	Tk. 87.00	Tk. 88.00	Tk. 88.00
32.33.1	Replacing of 75 mm long galvanized iron catch hook	each	Tk. 17.00	Tk. 17.00	Tk. 16.00	Tk. 16.00

[Handwritten signatures and notes in blue ink at the bottom of the page, including names like 'Anwar' and various initials.]

Item No.	Description of Item	Unit	Unit Rate (Dhaka, Mymensingh)	Unit Rate (Chattogram, Sylhet)	Unit Rate (Khulna, Barisal, Gopalganj)	Unit Rate (Rajshahi, Rangpur)
32.33.2	Replacing of 100 mm long galvanized iron catch hook	each	Tk. 19.00	Tk. 19.00	Tk. 19.00	Tk. 19.00
32.33.3	Replacing of 150 mm long galvanized iron catch hook	each	Tk. 22.00	Tk. 22.00	Tk. 21.00	Tk. 21.00
32.33.4	Replacing of 200 mm long galvanized iron catch hook	each	Tk. 24.00	Tk. 24.00	Tk. 23.00	Tk. 23.00
32.33.5	Replacing of 225 mm long galvanized iron catch hook	each	Tk. 32.00	Tk. 32.00	Tk. 31.00	Tk. 31.00
32.34	Replacing of iron socket bolt : 50 mm dia, 100 mm long	each	Tk. 30.00	Tk. 30.00	Tk. 29.00	Tk. 29.00
32.35.1	Replacing of SS socket bolt : 50 mm dia, 100 mm long (SS)	each	Tk. 66.00	Tk. 66.00	Tk. 65.00	Tk. 65.00
32.35.2	Replacing of iron socket bolt : 50 mm dia, 150 mm long	each	Tk. 36.00	Tk. 36.00	Tk. 35.00	Tk. 35.00
32.35.3	Replacing of SS socket bolt : 50 mm dia, 150 mm long(SS)	each	Tk. 94.00	Tk. 94.00	Tk. 93.00	Tk. 93.00
32.35.4	Replacing of iron socket bolt : 50 mm dia, 200 mm long	each	Tk. 51.00	Tk. 51.00	Tk. 51.00	Tk. 51.00
32.35.5	Replacing of SS socket bolt : 50 mm dia, 200 mm long(SS)	each	Tk. 118.00	Tk. 118.00	Tk. 117.00	Tk. 117.00
32.36.1	Replacing of brass socket bolt: 50 mm dia, 150 mm long	each	Tk. 170.00	Tk. 170.00	Tk. 170.00	Tk. 170.00
32.36.2	Replacing of brass socket bolt : 50 mm dia, 200 mm long	each	Tk. 217.00	Tk. 217.00	Tk. 216.00	Tk. 216.00
32.36.3	Replacing of brass socket bolt : 50 mm dia, 250 mm long	each	Tk. 266.00	Tk. 266.00	Tk. 265.00	Tk. 265.00
32.37.1	Replacing of 75 mm long iron hinge	each	Tk. 52.00	Tk. 52.00	Tk. 51.00	Tk. 51.00
32.37.2	Replacing of 100 mm long iron hinge	each	Tk. 82.00	Tk. 82.00	Tk. 81.00	Tk. 81.00
32.38.1	Replacing of 75 mm long brass hinge	each	Tk. 164.00	Tk. 164.00	Tk. 163.00	Tk. 163.00
32.38.2	Replacing of 100 mm long brass hinge	each	Tk. 217.00	Tk. 217.00	Tk. 216.00	Tk. 216.00
32.39.1	Replacing of 50 mm dia iron ring	each	Tk. 32.00	Tk. 32.00	Tk. 31.00	Tk. 31.00
32.39.2	Replacing of 50 mm dia brass ring	each	Tk. 65.00	Tk. 65.00	Tk. 64.00	Tk. 64.00
32.40.1	Supplying, fitting and fixing of 25 x 25 mm expanded mesh metal net of wooden or steel frame (excluding the cost of wood or steel sections and painting)	sqm	Tk. 1,108.00	Tk. 1,107.00	Tk. 1,042.00	Tk. 1,042.00
32.40.2	Supplying, fitting and fixing of 25 x 25 mm expanded mesh metal net in F.I. Bar frame (including the cost of F.I. Bar)	sqm	Tk. 2,083.00	Tk. 2,082.00	Tk. 2,000.00	Tk. 2,000.00
32.41.1	Renewing of white washing: 1 coat	sqm	Tk. 15.00	Tk. 15.00	Tk. 14.00	Tk. 14.00
32.41.2	Renewing of white washing: 2 coats	sqm	Tk. 22.00	Tk. 22.00	Tk. 20.00	Tk. 20.00
32.42.1	Renewing of colour washing with yellow ochre: 1 coat	sqm	Tk. 23.00	Tk. 23.00	Tk. 22.00	Tk. 22.00
32.42.2	Renewing of colour washing with yellow ochre: 2 coats	sqm	Tk. 26.00	Tk. 26.00	Tk. 24.00	Tk. 24.00
32.43.1	Renewing of Exterior standard acrylic emulsion paint of approved brand and quality	sqm	Tk. 153.00	Tk. 152.00	Tk. 144.00	Tk. 144.00
32.43.2	Renewing of Exterior premium acrylic emulsion paint of approved brand and quality	sqm	Tk. 177.00	Tk. 175.00	Tk. 166.00	Tk. 166.00
32.44.1	Renewing of standard synthetic enamel paint to door-windows frame and shutter:1coats	sqm	Tk. 119.00	Tk. 118.00	Tk. 111.00	Tk. 111.00
32.44.2	Renewing of premium synthetic enamel paint to door-windows frame and shutter: 1coats	sqm	Tk. 123.00	Tk. 122.00	Tk. 115.00	Tk. 115.00
32.45.1	Renewing of standard synthetic enamel paint to door-windows frame and shutter: 2 coat	sqm	Tk. 183.00	Tk. 181.00	Tk. 170.00	Tk. 170.00
32.45.2	Renewing of premium synthetic enamel paint to door-windows frame and shutter: 2coat	sqm	Tk. 191.00	Tk. 189.00	Tk. 178.00	Tk. 178.00
32.46.1	Renewing of synthetic polyvinyl distemper : 1 coats	sqm	Tk. 96.00	Tk. 95.00	Tk. 89.00	Tk. 89.00
32.46.2	Renewing of synthetic polyvinyl distemper : 2 coat	sqm	Tk. 138.00	Tk. 137.00	Tk. 128.00	Tk. 128.00
32.47.1	Renewing of Interior standard acrylic emulsion paint (Plastic) to walls and ceiling: 1 coat	sqm	Tk. 108.00	Tk. 107.00	Tk. 101.00	Tk. 101.00
32.47.2	Renewing of Interior Premium acrylic emulsion painting (silky finish)to walls and ceiling: 1 coat	sqm	Tk. 124.00	Tk. 124.00	Tk. 117.00	Tk. 117.00
32.47.3	Renewing of Interior super premium acrylic emulsion painting (odorless) to walls and ceiling: 1 coat	sqm	Tk. 144.00	Tk. 143.00	Tk. 137.00	Tk. 137.00
32.48.1	Renewing of Interior standard acrylic emulsion paint (Plastic) to walls and ceiling: 2 coat	sqm	Tk. 155.00	Tk. 154.00	Tk. 145.00	Tk. 145.00

Handwritten signatures and initials in blue ink at the bottom of the page.

Item No.	Description of Item	Unit	Unit Rate (Dhaka, Mymensingh)	Unit Rate (Chattogram, Sylhet)	Unit Rate (Khulna, Barisal, Gopalganj)	Unit Rate (Rajshahi, Rangpur)
32.71.6	300 mm x 300 mm size earthen plate	each	Tk. 37.00	Tk. 37.00	Tk. 37.00	Tk. 37.00
32.71.7	Supply of mustard oil-cake	kg	Tk. 56.00	Tk. 56.00	Tk. 56.00	Tk. 56.00
32.71.8	Supply of Bone meal	kg	Tk. 55.00	Tk. 55.00	Tk. 55.00	Tk. 55.00
32.71.9	Supply of steel spade	each	Tk. 552.00	Tk. 552.00	Tk. 552.00	Tk. 552.00
32.71.10	Supply of Urea fertilizer	kg	Tk. 31.00	Tk. 31.00	Tk. 31.00	Tk. 31.00
32.71.11	Supply of Murate of potash	kg	Tk. 27.00	Tk. 27.00	Tk. 27.00	Tk. 27.00
32.71.12	Supply of T. S. P.	kg	Tk. 37.00	Tk. 37.00	Tk. 37.00	Tk. 37.00
32.71.13	Supply of 5 liter capacity spray machine (plastic)	each	Tk. 2,209.00	Tk. 2,209.00	Tk. 2,209.00	Tk. 2,209.00
32.71.14	Supply of 450 mm size Steel funna with wooden handle	each	Tk. 454.00	Tk. 454.00	Tk. 454.00	Tk. 454.00
32.71.15	Supply of 225 mm long hand hoe with wooden handle	each	Tk. 123.00	Tk. 123.00	Tk. 123.00	Tk. 123.00
32.71.16	Supply of standard steel hand trolley as per direction of officer-in-charge	each	Tk. 7,608.00	Tk. 7,608.00	Tk. 7,608.00	Tk. 7,608.00
32.71.17	Supply of China made or equivalent Hedge Scissors	each	Tk. 1,472.00	Tk. 1,472.00	Tk. 1,472.00	Tk. 1,472.00
32.71.18	Supply of 250 mm size China made or equivalent Secature	each	Tk. 798.00	Tk. 798.00	Tk. 798.00	Tk. 798.00
32.71.19	Supply of 2.5 gallon capacity 22 BWG G.I. Water cane	each	Tk. 429.00	Tk. 429.00	Tk. 429.00	Tk. 429.00
32.71.20	Supply of 350 mm size G.I. bucket	each	Tk. 344.00	Tk. 344.00	Tk. 344.00	Tk. 344.00
32.71.21	Supply of best quality 19 mm dia plastic hose pipe	each	Tk. 22.00	Tk. 22.00	Tk. 22.00	Tk. 22.00
32.71.22	Supply of insecticide perfecthion 40 EC 1 pic, 100ml bottle	each	Tk. 301.00	Tk. 301.00	Tk. 301.00	Tk. 301.00
32.71.23	Supply of Redomil gold 68WG (metalexil+mencojeb) 1 pack, 500gm pack	each	Tk. 1,012.00	Tk. 1,012.00	Tk. 1,012.00	Tk. 1,012.00
32.71.24	Supply of Ripcord 400EC, 1 pic, 100ml bottle	each	Tk. 270.00	Tk. 270.00	Tk. 270.00	Tk. 270.00
32.71.25	Supply of Proclaim 5SG(emamectin benzoet) 1 box, (10 pack, each pack 10gm)	each	Tk. 779.00	Tk. 779.00	Tk. 779.00	Tk. 779.00
32.71.26	Supply of Vertimec 018ECG (ebamectin) 1 pic, 50ml bottle	each	Tk. 147.00	Tk. 147.00	Tk. 147.00	Tk. 147.00
32.72	Painting to earthen tub: 2 coats over a prime coat					
32.72.1	200mm and 250mm size tub	each	Tk. 22.00	Tk. 22.00	Tk. 20.00	Tk. 20.00
32.72.2	300 mm, 350mm and 400 mm size tub	each	Tk. 35.00	Tk. 34.00	Tk. 33.00	Tk. 33.00
32.73.1	Levelling & dressing the compound or plant/flower bed as per direction of Engineer-in-charge.	sqm	Tk. 9.00	Tk. 9.00	Tk. 8.00	Tk. 8.00
32.73.2	Lawn grass cutting, dressing, brooming and removing debris etc. as per direction of Officer in charge	sqm	Tk. 17.00	Tk. 16.00	Tk. 15.00	Tk. 15.00
32.73.3	Spading, pulverizing soil lump etc. as per direction of Officer in charge	sqm	Tk. 6.00	Tk. 6.00	Tk. 5.00	Tk. 5.00
32.74.1	Labour for picking-up and cleaning damaged bituminous road surface	sqm	Tk. 77.00	Tk. 76.00	Tk. 70.00	Tk. 70.00
32.74.2	Repairing the potholes of the road by picking up and removing damaged materials with stone chips	cum	Tk. 30,553.00	Tk. 30,410.00	Tk. 29,068.00	Tk. 28,681.00
31.75	Applying necessary coat of bitumenous aluminium paint seal-coat on top surface of newly laid roofing felt	sqm	Tk. 106.00	Tk. 105.00	Tk. 101.00	Tk. 101.00
32.76.1	Supplying timber (unfinished) for repairing in wood works: Garjan/Jam/Local Sal	cum	Tk. 95,331.00	Tk. 90,998.00	Tk. 97,498.00	Tk. 97,498.00
32.76.2	Supplying timber (unfinished) for repairing in wood works: Jarul	cum	Tk. 77,998.00	Tk. 77,998.00	Tk. 77,998.00	Tk. 77,998.00
32.76.3	Supplying timber (unfinished) for repairing in wood works: Shilkorai/Chickrashi	cum	Tk. 108,331.00	Tk. 108,331.00	Tk. 108,331.00	Tk. 108,331.00
32.76.4	Supplying timber (unfinished) for repairing in wood works: Teak Chambal	cum	Tk. 160,330.00	Tk. 155,997.00	Tk. 162,497.00	Tk. 162,497.00
32.76.5	Supplying timber (unfinished) for repairing in wood works: Chattogram Teak	cum	Tk. 190,663.00	Tk. 186,330.00	Tk. 199,286.00	Tk. 199,286.00
32.76.6	Supplying timber (unfinished) for repairing in wood works: Kathal	cum	Tk. 103,998.00	Tk. 103,998.00	Tk. 103,998.00	Tk. 103,998.00
32.76.7	Supplying timber (unfinished) for repairing in wood works: Gamari	cum	Tk. 82,332.00	Tk. 77,998.00	Tk. 86,665.00	Tk. 86,665.00

Handwritten signatures and initials in blue ink are present at the bottom of the page, including a large signature on the left and several smaller initials and marks across the bottom.

Item No.	Description of Item	Unit	Unit Rate (Dhaka, Mymensingh)	Unit Rate (Chattogram, Sylhet)	Unit Rate (Khulna, Barisal, Gopalganj)	Unit Rate (Rajshahi, Rangpur)
32.76.8	Supplying timber (unfinished) for repairing in wood works: Chapalish	cum	Tk. 99,665.00	Tk. 95,331.00	Tk. 103,998.00	Tk. 103,998.00
32.76.9	Supplying timber (unfinished) for repairing in wood works: Loha/Pyiankado	cum	Tk. 116,998.00	Tk. 116,998.00	Tk. 116,998.00	Tk. 116,998.00
32.76.10	Supplying timber (unfinished) for repairing in wood works: Myanmar(Burma) teak	cum	Tk. 307,660.00	Tk. 303,327.00	Tk. 311,994.00	Tk. 311,994.00
32.76.11	Supplying timber (unfinished) for repairing in wood works: Ordinary timber (Mehogoni)	cum	Tk. 86,665.00	Tk. 86,665.00	Tk. 86,665.00	Tk. 86,665.00
32.77	Labour charge for cleaning, washing, brooming from all heights and stacking of debris at a place beyond plinth area of the the site during execution of repair works as per direction of the engineer-in-charge	cum	Tk. 1,451.00	Tk. 1,425.00	Tk. 1,319.00	Tk. 1,319.00
32.78	Cleaning, washing, brooming and taking away of debris from the site during and or after the completion of the repair works in all heights by truck or by any other means as per direction of the engineer-in-charge	cum	Tk. 808.00	Tk. 798.00	Tk. 757.00	Tk. 757.00
32.79	Repairing of steel grill/window frame and shutter/stair railing, veranda grill, rolling shutter excluding the cost of steel materials.	sqm	Tk. 916.00	Tk. 902.00	Tk. 839.00	Tk. 839.00
32.80	Supply of steel materials for repairing work:					
32.80.1	40-grade deform bar	kg	Tk. 80.00	Tk. 80.00	Tk. 80.00	Tk. 80.00
32.80.2	60-grade deform bar	kg	Tk. 88.00	Tk. 88.00	Tk. 88.00	Tk. 88.00
32.80.3	M.S. angle, T, and Z - section, Channel etc.	kg	Tk. 86.00	Tk. 86.00	Tk. 86.00	Tk. 86.00
32.80.4	M.S. plain bar, F.I. Bar	kg	Tk. 86.00	Tk. 86.00	Tk. 86.00	Tk. 86.00
32.80.5	M.S. sheet, plate used in repairing work	kg	Tk. 94.00	Tk. 94.00	Tk. 94.00	Tk. 94.00
32.80.6	38mm dia G.I. Pipe used in repairing work	meter	Tk. 705.00	Tk. 705.00	Tk. 705.00	Tk. 705.00
32.80.7	25mm dia G.I. Pipe used in repairing work	meter	Tk. 322.00	Tk. 322.00	Tk. 322.00	Tk. 322.00
32.80.8	20 mm dia G.I. Pipe used in repairing work	meter	Tk. 330.00	Tk. 330.00	Tk. 330.00	Tk. 330.00
32.80.9	12mm dia G.I. Pipe used in repairing work	meter	Tk. 246.00	Tk. 246.00	Tk. 246.00	Tk. 246.00
32.80.10	Spring for rolling shutter used in repairing work	meter	Tk. 72.00	Tk. 72.00	Tk. 72.00	Tk. 72.00
32.80.11	Spring box for rolling shutter used in repairing work	each	Tk. 160.00	Tk. 160.00	Tk. 160.00	Tk. 160.00
32.81	Cleaning and mending good the damages surrounding the mouth of spout/rain water down pipe	each	Tk. 172.00	Tk. 171.00	Tk. 158.00	Tk. 158.00
32.82	Cleaning rain water down pipe	meter	Tk. 6.00	Tk. 6.00	Tk. 6.00	Tk. 6.00
32.83	Cleaning, renewing of drain and apron with cement concrete or cement mortar etc as per direction of Engineer-in-charge.	meter	Tk. 232.00	Tk. 231.00	Tk. 220.00	Tk. 219.00
32.84.1	Reexcavation of kutchra drain of 0.30 m width and average 0.6 m deep	meter	Tk. 31.00	Tk. 30.00	Tk. 28.00	Tk. 28.00
32.84.2	Reexcavation of kutchra drain of 0.61 m width and average 1.22 m deep	meter	Tk. 125.00	Tk. 123.00	Tk. 114.00	Tk. 114.00
32.85	Clearing choked up masonry surface drain	meter	Tk. 31.00	Tk. 31.00	Tk. 29.00	Tk. 29.00
32.86	Clearing silt from soak well up to 1.4 m dia	each	Tk. 2,098.00	Tk. 2,096.00	Tk. 1,963.00	Tk. 1,963.00
32.87	Clearing sludges & night soil from septic tank removing to a safe place/distance without affecting environment					
32.87.1	10 usser septic tank	each	Tk. 2,393.00	Tk. 2,380.00	Tk. 2,270.00	Tk. 2,270.00
32.87.2	20 user septic tank	each	Tk. 3,374.00	Tk. 3,362.00	Tk. 3,190.00	Tk. 3,190.00
32.87.3	30 user septic tank	each	Tk. 3,865.00	Tk. 3,853.00	Tk. 3,650.00	Tk. 3,650.00
32.87.4	50 user septic tank	each	Tk. 6,074.00	Tk. 6,062.00	Tk. 5,767.00	Tk. 5,767.00
32.87.5	100 user septic tank	each	Tk. 10,491.00	Tk. 10,479.00	Tk. 10,000.00	Tk. 10,000.00
32.87.6	200 user septic tank	each	Tk. 18,344.00	Tk. 18,332.00	Tk. 17,546.00	Tk. 17,546.00

Handwritten signatures and initials in blue ink at the bottom of the page.

Item No.	Description of Item	Unit	Unit Rate (Dhaka, Mymensingh)	Unit Rate (Chattogram, Sylhet)	Unit Rate (Khulna, Barisal, Gopalganj)	Unit Rate (Rajshahi, Rangpur)
32.109	Cleaning under ground water reservoir and removing the waste to safe place/ distance from building site without affecting the environment etc. All completed as per direction of Engineer- in charge. (If water reservoir tank capacity is more then 10,000 gallon then unit price for additional gallon will be reduced by @ 25% of unit price)	per gallon	Tk. 0.86	Tk. 0.85	Tk. 0.83	Tk. 0.83
32.110	Cleaning and removing inside rust from existing old GI pipe of different dia meter etc. All completed as per direction of Engineer- in charge.	per meter	Tk. 4.10	Tk. 4.10	Tk. 3.90	Tk. 3.90
32.111	Taking out old unserviceable MS window shutter/grill etc. All completed as per direction of Engineer- in charge.	each	Tk. 202.00	Tk. 199.00	Tk. 190.00	Tk. 190.00
32.112	Taking out unserviceable old MS collapsible gate and refitting after minor repair (excluding cost of material) etc. All completed as per direction of Engineer- in charge.	each	Tk. 2,587.00	Tk. 2,550.00	Tk. 2,432.00	Tk. 2,430.00
32.113	Picking & uprooting unwanted tree, plants etc from building /structure and removing to safe distance from building/structure and using chemicals to prevent further growing up. All completed as per direction of Engineer- in charge.	each	Tk. 242.00	Tk. 239.00	Tk. 227.00	Tk. 227.00
32.114	Sanitary blockage removal of Combi-closet, commode, Long Pan etc. All completed as per direction of Engineer- in charge.	each	Tk. 368.00	Tk. 368.00	Tk. 353.00	Tk. 353.00
32.115	Sanitary blockage removal of Basin, Sink, waste water down pipe etc. All completed as per direction of Engineer- in charge.	each	Tk. 160.00	Tk. 160.00	Tk. 153.00	Tk. 153.00
32.116	Writing & providing of name plate or Flat/Room numbering on Acrylic transparent sheet including fitting fixing etc. All completed as per direction of Engineer- in charge.	each	Tk. 1,497.00	Tk. 1,497.00	Tk. 1,491.00	Tk. 1,491.00
32.117	Hire charge of mechanical gondola for repair work of high rise building height above 20 meter etc. All completed as per direction of Engineer- in charge.	per day	Tk. 2,454.00	Tk. 2,454.00	Tk. 2,393.00	Tk. 2,393.00
32.118	Taking out old unserviceable Aluminium Door/window frame and shutter etc. All completed as per direction of Engineer- in charge.	each	Tk. 245.00	Tk. 240.00	Tk. 227.00	Tk. 227.00
..... END OF CHAPTER THIRTY TWO						